



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date:

July 19, 2010

Reviewed: 

Mine Name: A to Z Minerals	Permit Number: S0230075
Operator Name: Gold Canyon Mining & Development	Inspection Date: 07/13/2010
Inspector(s): Wayne Western	Time: 3:10- 3:20 pm
Other Participants: None	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: The Permittee posted a \$10,000 with the BLM. In a letter from the BLM dated April 20, 2009, the BLM stated that they were forfeiting the bond because the Permittee failed to remove personal property and reclaim the site. In a phone call on July 19, 2010 between Jerry Mansfield of the BLM and Wayne Western of DOGM, the BLM agreed to proceed with bond forfeiture and coordinate reclamation with DOGM.


Permit fee: Delinquent since 2007.

Purpose of Inspection: This was a routine annual inspection.

Inspection Summary: The site had not been reclaimed. The camera was not working so no photos were taken.

Conclusions and Recommendations: The Division should coordinate with the BLM on bond forfeiture.

Inspector's Signature
WHW



Inspection Date: 07/13/2010

Page 2 of 2

S/023/0075

cc: Donell Adair

Jerry_Mansfield@BLM.gov – BLM